

Date: 2-19-26



Region: 4A

FEMS/CSS No.: 3497215

FAC ID: PA209

Maximo WO No.: 21453

Asset #:

Priority: 2

Original Work Request:

Boiler #1 continues to have the blower fault lockout. This has been an ongoing issue but is happening more often. It has already been reset at least 4 times this morning.

Description of Repairs Needed:

Proposal is to replace boiler #1 controller, program controller and startup and check for proper operation.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1) - Investigation	2.5	\$ 179.00	\$ 447.50
Trip charge - Investigation	1	\$ 180.00	\$ 180.00
Tech (1) - Repair	8	\$ 179.00	\$ 1,432.00
Trip charge - Repair	1	\$ 180.00	\$ 180.00

Material List:	Quantity	Cost	Total
Controller (W384000255)	1	\$ 490.00	\$ 490.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,239.50	\$490.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,729.50	\$327.54	\$163.77	\$3,220.81