

Date: 6/27/2023

Region: 4A
FAC ID: NY052

CSS No.: 92877
Maximo WO No.: 12542

Asset #: 6589

Priority: Urgent



Original Work Request:

Boiler will not operate. Troubleshoot and repair boiler #1. Lockout Fan Speed is the error message

Description of Repairs Needed:

Labor and material to a.) trouble shoot boiler not working b.) Order replacement failed inducer assembly. c.) Pick up and install new fan motor on boiler (Lochinvar part number 100188877)

Labor:	Labor Hrs	Labor Rate	Total
Technician	14	\$ 99.00	\$ 1,386.00
			\$ -

Material List:	Quantity	Cost	Total
Lochinvar PN# 100188877	1	\$2,227.00	\$ 2,227.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

12729

Estimate Summary:

Labor	Material	Equipment
\$1,386.00	\$2,227.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,613.00	\$433.56	\$216.78	\$4,263.34