

Date: 1/16/2024

Region: 4A  
FAC ID: NY030

CSS No.: 96226  
Maximo WO No.: 14785



Asset #: NA

Priority: Routine

**Original Work Request:**

Repair heater in OMS building. HVAC Tech found that control board and fuse in heating are blown. They need replacement to further repair heater.

**Description of Repairs Needed:**

Labor and material to a.) repair the floor heater by replacing the control board and the fuse.

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician	4	\$ 128.00	\$ 512.00
Trip Charge	1	\$ 50.00	\$ 50.00

**Material List:**

	Quantity	Cost	Total
Control Board & Fuse	1	\$ 539.00	\$ 539.00
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 562.00	\$ 539.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,101.00	\$132.12	\$66.06	\$1,299.18



January 16, 2024

Tidewater, Inc  
US Army Corps of Engineers  
Horseheads, NY 14850

Attn: Karlee Demain

Re: Heater repair Horseheads CSS95150

Ms. Demain,

Postler & Jaeckle Service is pleased to provide a quote to repair the floor heater and the Horseheads facility. Your cost for this service will be \$512.00 labor, \$539.00 materials, and \$50.00 truck charge for a total of \$1,101.00. Thank you for the opportunity to provide this quote for your facility. Please contact me with any questions.

Sincerely,

**DAVE HENDEE**  
Field Sales Support  
**Postler & Jaeckle Corp.**  
**2000 Lake Rd., Elmira, NY 14903**  
**T 607-739-8303 | C 607-215-6523**  
E: [dhendee@postler.com](mailto:dhendee@postler.com)