

CMI Management  
Bowie Army Reserve Center  
4600 Foxtail Place  
White Plains MD 20695  
(202) 437-5119

Report Number: 11603

Recorded By: James Harris  
(410) 991-7190  
jharris@bondwater.com

Report Type: General

**4600 Foxtail Place - HVAC**

Lab results for all 3 wells is attached with this report. The final lab results were received 10/25 once the oil analysis was completed but I neglected to send it at that time.

Bond Water Technologies, Inc. recommends that you perform regular and/or daily analysis to control chemical levels and cycles of concentration within established limits. Test results reflect conditions during the point in time when the analysis was performed. Additional testing may be performed upon request. As operating conditions vary, test results will change over time. Notwithstanding anything to the contrary contained in the Agreement or otherwise, (i) Bond Water Technologies and its Insurers are not liable for losses caused by the Customer's wrongful acts or omissions, (ii) Bond's program does not cover and it makes no guarantees with respect to waterborne pathogens including Legionella or against health risks therefrom, and (iii) in no event shall either party be liable for any consequential or indirect damages.