



CUSTOMER QUOTATION NO. 552

CMI Management, Inc.
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 13953
Quote No: 552
Site: MD066 Fox Tail Avenue
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 03/24/2021
Valid For: 30 Day(s)

WO#: 13953

CSS Ticket Number: 29565

Problem: Bent drive shaft, this is needed before it fails.

S&S is sending this quote to CMI to remove and reinstall new shaft into WSHP unit.

S&S will remove fan assembly in WSHP unit.

S&S will remove old shaft from fan assembly.

S&S will install new shaft and the 3 fan assemblies onto new Daikin supplied shaft.

S&S will reinstall new shaft and fan assembly into WSHP unit.

S&S will reinstall new pulley and belts to unit and perform full operation checks.

Service

Item	Quantity	Unit Price	Total
Blower Pulley/ 802023076	1.00	\$179.46	\$179.46
Shaft/802023058	1.00	\$1,171.38	\$1,171.38
Key / 802023047	1.00	\$22.50	\$22.50
Pillow Block Bearings/ 44392	2.00	\$200.34	\$400.68
Shipping	1.00	\$200.00	\$200.00
Diagnosis Fee	1	\$800.00	\$800.00
HVAC Labor Rate	40	\$100.00	\$4,000.00
Sub-Total ex Tax			\$6,774.02
Tax			\$0.00
Total inc Tax			\$6,774.02

Labor	\$4,800.00
Materials	\$1,974.02
Sub-Total ex Tax	\$6,774.02
Tax	\$0.00
Total inc Tax	\$6,774.02