

Date: 2/23/2024

Region: 4A
FAC ID: NY030

CSS No.: 96226
Maximo WO No.: 14785



Asset #: NA

Priority: Routine

Original Work Request:

Repair heater in OMS building. HVAC Tech found that control board and fuse in heating are blown. They need replacement to further repair heater.

Description of Repairs Needed:

Labor and material to a.) replace the Condensate pump p/n 554642 b.) install (4) 16x20x2 pleated filters
c.) install (2) 16x16x2 pleated filters d.) install Fan sheave p/n 1VP4058 e.) install a Belt p/n A-59

Labor:

	Labor Hrs	Labor Rate	Total
Technician	4	\$ 128.00	\$ 512.00
Trip Charge	1	\$ 50.00	\$ 50.00

Material List:

	Quantity	Cost	Total
Misc. Materials listed above	1	\$ 539.00	\$ 539.00
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 562.00	\$ 539.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,101.00	\$132.12	\$66.06	\$1,299.18



January 16, 2024

Tidewater, Inc
US Army Corps of Engineers
Horseheads, NY 14850

Attn: Karlee Demain

Re: Heater repair Horseheads CSS95150

Ms. Demain,

Postler & Jaeckle Service is pleased to provide a quote to repair the floor heater and the Horseheads facility. Your cost for this service will be \$512.00 labor, \$539.00 materials, and \$50.00 truck charge for a total of \$1,101.00. Thank you for the opportunity to provide this quote for your facility. Please contact me with any questions.

Sincerely,

DAVE HENDEE
Field Sales Support
Postler & Jaeckle Corp.
2000 Lake Rd., Elmira, NY 14903
T 607-739-8303 | C 607-215-6523
E: dhendee@postler.com