

Date: 7/6/2023

Region: 4C

CSS No.: 92029

FAC ID: WV014

Maximo WO No.: 12089

Asset #: NA

Priority: Routine



Original Work Request:

Repair outdoor IDS speaker and existing wiring. Replace outdoor siren in front of building.

Description of Repairs Needed:

Labor and material to a.) to diagnose repair/replace (2) exterior IDS Vault Sirens at the Grafton, WV USARC. Please note: Contractor shall utilize existing Wiring.

Labor:

	Labor Hrs	Labor Rate	Total
Technician (2 Men 8 Hrs)	8	\$ 85.00	\$ 1,360.00
		\$ -	\$ -

Material List:

	Quantity	Cost	Total
2 IDS Sirens Amesco Potter SSX-52S	1	\$ 254.00	\$ 254.00
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,360.00	\$ 254.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,614.00	\$193.68	\$96.84	\$1,904.52

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 2218**DATE** 03/22/2023**P.O. NUMBER**

Grafton, WV USARC (2) Sirens

	ACTIVITY	QTY	AMOUNT
03/22/2023	Services Grafton, WV USARC Repair/Replace (2) Ext. Vault Sirens CSS# 92029	1	1,614.00

Dear Ms. Demain,

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose, repair/replace (2) exterior IDS Vault Sirens at the Grafton, WV USARC. Contractor shall utilize existing Wiring.

Cost Breakdown:

(2) IDS Sirens.....\$254.00
 (2) men 8 hrs @ \$85.....\$1,360.00

Grand Total.....\$1,614.00

The cost for the above mentioned work is \$1,614.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$1,614.00

Accepted By

Accepted Date