

Over and Above Estimate

Region: 5

Location: MD019

CSS #: 19564

Maximo Work Order No.: 9032

Asset #: 1243

Date: 6/5/2019

Original Description:

An issue with the vault door not opening or closing properly. The vault is currently secured though. The tenants are hesitant to open the door at this time for concern of being able to close and secure it again.

Repairs Needed:

Labor and materials to a.) replace Qty (1) current lock on the vault door with the same lock (SG8410-014). b.) Labor to install an S&G primary lock with the vault, switching over from the electric lock. NOTE: GSA standard check for the vault to make sure all federal requirements meet when replacing the lock. This is a requirement for the vault to certified must replace lock.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Labor 2 Technicians	12	\$150.00	--	--	\$1,900.00
1	NA	SG2937 Lock	--	--	\$1,180.00	--	\$1,180.00
1	NA	S&G primary lock	--	--	\$915.00	--	\$915.00
--	NA	Diagnostic Fee	--	--	--	--	\$250.00
2	NA	GSA Standard	--	--	--	--	\$300.00
--	NA	CMI Coordination and Site/Task Oversight	6	\$80.00	--	--	\$480.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
18	\$2,630.00	\$2,395.00	--	\$5,025.00	102%	\$5,125.50

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com



Estimate

Date	Estimate #
5/30/2019	28737

Customer Information
Tidewater PM 3761 Attucks Drive Powell, OH 43065

Item	Description	Qty	Cost	Total
S&G Dail Lock	S&G primary lock for the 99th region as switching over from the electric lock.	1	915.00	915.00T
LABOR	Labor to install lock on vault with experience locksmith. Labor to remove existing lock. 4-6 hours.	1	950.00	950.00
gsa check	GSA standard check for the vault to make sure all federal requirments meet when replacing the lock. This is requirment for the vault to certified must replace lock.	1	150.00	150.00T
SERVICE CALL	Service Call for going out accessing vault and finding the solution for repair. Date visit: 08/03/19 Seperate charge from replacing lock.	1	250.00	250.00

WE LOOK FORWARD TO ASSISTING YOU!		Subtotal	\$2,265.00
Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.		Sales Tax (0.0%)	\$0.00
SIGNATURE: _____		Total	\$2,265.00
DATE: _____			
Terms: 50% deposit and 50% due upon completion			

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com



Estimate

Date	Estimate #
5/30/2019	28739

Customer Information
Tidewater PM 3761 Attucks Drive Powell, OH 43065

Item	Description	Qty	Cost	Total
Buterfly Military ...	Confirmation this lock is the SG2937. The butterfly lock needs a certain part for the SG2937 which would be a different cost. Here is 20% mark up.	1	1,180.00	1,180.00
LABOR	Labor to replace current lock on the door. Lock is currently getting jammed and the access military personnel is having a rough time opening it. 4-6 hours.	1	950.00	950.00
gsa check	GSA standard check on the door that is secured. Adam this is another quote for a door that is in the vault that he can not get into because of the lock constantly getting stuck and jammed. Again, this door is inside the vault securing something. This lock needs to be replaced immediately. Call me if you have any questions. Hunter Alderman 443-929-1985	1	150.00	150.00

WE LOOK FORWARD TO ASSISTING YOU!		Subtotal	\$2,280.00
Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.		Sales Tax (0.0%)	\$0.00
SIGNATURE: _____		Total	\$2,280.00
DATE: _____			
Terms: 50% deposit and 50% due upon completion			

SPRING BRIDGES ADMINISTRATION
APPROVED
SECURITY UNIT NO. 100
Mosier

Technical Support Hotline 1-800-288-1000 or 800-955-0310
SECURED
220 East 11th Street, Suite 100, Des Moines, IA 50319

PROPERTY OF SPRING BRIDGES ADMINISTRATION		DATE: 11/11/2011	
TITLE: [illegible]		[illegible]	
1	[illegible]	2	[illegible]
3	[illegible]	4	[illegible]
5	[illegible]	6	[illegible]
7	[illegible]	8	[illegible]
9	[illegible]	10	[illegible]
11	[illegible]	12	[illegible]
13	[illegible]	14	[illegible]
15	[illegible]	16	[illegible]
17	[illegible]	18	[illegible]
19	[illegible]	20	[illegible]
21	[illegible]	22	[illegible]
23	[illegible]	24	[illegible]
25	[illegible]	26	[illegible]
27	[illegible]	28	[illegible]
29	[illegible]	30	[illegible]
31	[illegible]	32	[illegible]
33	[illegible]	34	[illegible]
35	[illegible]	36	[illegible]
37	[illegible]	38	[illegible]
39	[illegible]	40	[illegible]
41	[illegible]	42	[illegible]
43	[illegible]	44	[illegible]
45	[illegible]	46	[illegible]
47	[illegible]	48	[illegible]
49	[illegible]	50	[illegible]
51	[illegible]	52	[illegible]
53	[illegible]	54	[illegible]
55	[illegible]	56	[illegible]
57	[illegible]	58	[illegible]
59	[illegible]	60	[illegible]
61	[illegible]	62	[illegible]
63	[illegible]	64	[illegible]
65	[illegible]	66	[illegible]
67	[illegible]	68	[illegible]
69	[illegible]	70	[illegible]
71	[illegible]	72	[illegible]
73	[illegible]	74	[illegible]
75	[illegible]	76	[illegible]
77	[illegible]	78	[illegible]
79	[illegible]	80	[illegible]
81	[illegible]	82	[illegible]
83	[illegible]	84	[illegible]
85	[illegible]	86	[illegible]
87	[illegible]	88	[illegible]
89	[illegible]	90	[illegible]
91	[illegible]	92	[illegible]
93	[illegible]	94	[illegible]
95	[illegible]	96	[illegible]
97	[illegible]	98	[illegible]
99	[illegible]	100	[illegible]

