



Facility Repair Proposal

Region: 4A
Fac ID: PA118
Date: 1/27/23

CSS # 91459
Maximo Work Order No.: 11802

Asset ID: NA

Original Work Request:

Repair wall mounted LED light fixture in the AMSA high bay wall light is strobing.

Description of Repairs Needed:

Labor (approximately (6) hours) and material to a.) replace 3 Wall Mounted LED Light Fixtures in AMSA High Bay

Parts List:

LED Wall Lights

Equipment List: NA

PM History:

NA

Cost Proposal:

See attached RS Means Estimate.

Total Cost: \$1112.61

Estimate Name: CSS 91440 - WO 11767 - NY126 Change Out T-5 Light Bulbs

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 49 Jetview Drive, Chili, NY 14624
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2023	
						Labor Type: Repair & Remodeling	
						City Cost Index: NEW YORK / ROCHESTER (144-146)	
						</	