



Facility Repair Proposal

Region: 4A
Fac ID: NY126
Date: 01/26/23

CSS # 91440
Maximo Work Order No.: 11767

Asset ID: NA

Original Work Request:
Change out burned-out T-5 light bulbs in multiple fixtures.

Description of Repairs Needed:
Labor approximately (16) hours and material to a.) remove the ballast and battery backup for each emergency light that is not functioning properly b.) install new ballast, battery backup, and bulbs then test for proper operation.

Parts List: Emergency Fluorscent Ballast, 215W BODINE B30

FLUOR Ballast, Electronic, Programmed 28W

Linear FLUOR Bulb, T5, 21-5/8"

Linear FLUOR Bulb, T5, 45-1/4"

Equipment List: NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$12,277.94

Estimate Name: CSS 91440 - WO 11767 - NY126 Change Out T-5 Light Bulbs

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 49 Jetview Drive, Chili, NY 14624
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2023	
						Labor Type: Repair & Remodeling	
						City Cost Index: NEW YORK / ROCHESTER (144-146)	





