



Facility Repair Proposal

Region: 4A
Fac ID: NY126
Date: 2/8/23

CSS # 91701
Maximo Work Order No.: 12038

Asset ID: NA

Original Work Request:

Repair back double door of training building & install mullion & panic bars on double doors.

Description of Repairs Needed:

Labor (approximately 24 hours) and material to a.) install (2) Panic Bars, b.) (1) Mullion and c.) (1) Surface Mount HES 9600 Series Door Strike, d.) and (1) Exterior Handle for the Chili, NY Training Bldg Rear set of Double Doors

Parts List:

- (2) Arrow Panic Bars
- (1) Mullion
- (1) HES 9600 Series Surface Mount Door Strike
- (1) Exterior Handle

Equipment List: NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$4273.19

Estimate Name: CSS 91701 - WO 12038 - NY126 Repair Double Door of Training Bldg

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 49 Jetview Drive, Chili, NY 14624
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2023 Quarter 1	
						Labor Type: Repair & Remodeling	
						City Cost Index: NEW YORK / ROCHESTER (144-146)	



SECURITY ALERT
DO NOT
use these doors for in / out
access.
USE the supply area doors.

Do Not Use
Double Doors

Use Supply Door



SECURITY ALERT
DO NOT
use these doors for in / out
access.
USE the supply area doors.

Do Not Use
Double Doors

Use Supply Door

