



Date: 3/15/2023

Region: 4A

CSS No.: 91769

FAC ID: PA063

Maximo Work Order No.: 12051

Asset #: NA

Original Work Request:

Repair the overhead door to the drill hall in the training center. Top track bracket is broken and overhead door will not operate properly. Please see picture below.

Description of Repairs Needed:

Labor and material to a.) assess the door and parts needed for repair.b.) fabricate parts and replace mounting bracket.

Material List:

(1) Mounting Bracket

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
3	\$464.00	\$149.00	\$613.00



