



Date: 3/14/2023

Region: 4C
FAC ID: WV007

CSS No.: 92285
Maximo Work Order No.: 12334

Asset #: NA

Original Work Request:

During the PM for the boiler Casto tech found that a sensor on the chiller was bad and needs replaced.

Description of Repairs Needed:

Labor and material to a.) replace the loop temperature sensor b.) replacement of a flow switch for the chiller c.) suction line sensor on the Trane Chiller (M# CGAM080; S# U15B47125).

Material List:

(1)SENO2133 - TRANE
(1) SENO2039 - TRANE
(1) SWT03335 - TRANE

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
7	\$911.86	\$911.12	\$1,822.98