



Date: 5/26/2023

Region: 4C
FAC ID: VA012

CSS No.: 92080
Maximo Work Order No.: 12084

Asset #: NA

Original Work Request:

Replace 2 Pump in Vehicle Oil Motor Pool

Description of Repairs Needed:

Labor and material to a.) to replace the (2) pumps in the vehicle motor pool. (1) PM4 5:1 Universal Stub Pump w/Bung Adaptor (347120) (1) DF100 1" Pump Aluminum/Acetal (551010)

Material List:

(1) PM4 5:1 Universal Stub Pump w/Bung Adaptor (347120)
(1) DF100 1" Pump Aluminum/Acetal (551010)

Equipment List:


NA

PM WO History:

NA


Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
20	\$2,732.40	\$2,244.00	\$4,976.40



SAMSON CORPORATION
Swannanoa NC 28778
Phone 828 686 28778
PUMP TYPE: DF 100 8511
PART No.: 551015.300
YEAR: 07/18
MAX AIR / FLUID PRESSURE: 100 lpm - 26.5 US gpm
FLUID IN/OUT: 1" NPT + Flange
SERIAL No.: 551015X
FLUID IN/OUT: 1" NPT + Flange
SERIAL No.: 402738 7002

PATENTED WORLDWIDE V40
d-directflo®



COOL
SAMSON

Ne pointez pas la puissance de feu

Ne pas braquer le pistolet vers le corps. Danger.

Do not exceed max WPR of lowest rated system component.

No sobrepase la presión de trabajo del componente menos resistente.

Ne pas dépasser la pression de travail du composant le moins résistant.

Relieve air and fluid pressure in system before servicing.

Desconectar el aire y despresurizar el sistema para realizar servicio.

Deconnecter l'air, lacher la pression du système pour réaliser le service.

Legacy™

www.legacymfg.com

RATIO5:1/HD-S PUMPMASTER 4

PART No.: 347120.350

SERIAL No.: 000030083 0007 01/20

MAX. AIR PRESSURE: 10 Bar

MADE IN SPAIN

CE EAC



Legacy™



performance series

Part No.
L3553