



Date: 4/11/2023

Region: 4A
FAC ID: PA118

CSS No.: 92540
Maximo Work Order No.: 12369

Asset #: NA

Original Work Request:

The exhaust fan located on the wall in the gym room 101 is working properly. Repair the exhaust fan in the gym as the actuator is not working. The gym is in the warehouse building room #101

Description of Repairs Needed:

Labor and material to a.) replace (1) Johnson Controls M9216-BGA-2 modulator Motor

Material List:

(1) Johnson Controls M9216-BGA-2 modulator Motor

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
2	\$264.00	\$534.00	\$798.00