



Date: 4/3/2023

Region: 4A
FAC ID: PA062

CSS No.: 92729
Maximo Work Order No.: 12513

Asset #: 6610

Original Work Request:

Repair boiler #2 as it is making a loud squeaking noise while it is running. If not addressed, it cause further damage to the boiler.

Description of Repairs Needed:

Labor and material to a.) eplace the inducer on Boiler 2 Model: PF-399-N-REV 2o S/N: 5075876-201010

Material List:

(1) Inducer Model: PF-399-N-REV 2o S/N: 5075876-201010

Equipment List:

NA


PM WO History:

11111


Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$672.00	\$1,680.00	\$2,352.00

9490 RO



®



PeerlessBoilers.com



3097201

SERIES PUREFIRE BOILER

BOILER No.

PF-399-N-REV 2

SERIAL No.

5075876-201010

MAX. B.T.U. INPUT PER HR.

399000

MIN. B.T.U. INPUT PER HR.

80000

D.O.E. HTG. CAP. OR GROSS OUTPUT

373000

MAX. GAS SUPPLY PRESSURE IN. W.C.

13.5

MIN. GAS SUPPLY PRESSURE IN. W.C.

3.5

VALVE OUTLET PRESS. (TYP.) IN. W.C.

0 to .002

EQUIPPED FOR

NAT

GAS

CATEGORY NUMBER

IV

MIN. RELIEF VALVE CAPACITY

373

LB/HR OR MBH

NET I=B=R RATING

324000

B.T.U./HR.

THERMAL
EFFICIENCY %COMBUSTION
EFFICIENCY %

93.4

95.5

COMPLIES WITH ASHRAE 90.1, 2001

b-2007.CSA 4.9b

LOW PRESS. BOILERS

MAWP - WATER 160PSI MAXIMUM WATER TEMP. - 210°F
115 VOLTS - 60 HZ - LESS THAN 12 AMPS

PB HEAT, LLC

BALLY, PA 19503

X-8131 RO

FASCO

NO 70500106 Class B E333503
Type 50DB 3.7 A 60° C Amp
120 V 50/60 Hz 10000 Max RPM PH 1
300 Max Watts
Controller Type SG03 E.P.
Controller no. 81104137
Assembled In Mexico
Cust P/N 54665 03-15N
S/N NA150001688