



Date: 5/24/2023

Region: 4A
FAC ID: NY010

CSS No.: 92950
Maximo Work Order No.: 12571

Asset #: NA

Original Work Request:

The pot feeder and associated piping and valves needs repaired or replaced.

Description of Repairs Needed:

Labor and material to a.) shut down and drain the system remove the existing pot feeder, lines ,and valves b.) replace with a new pot feeder and new lines and valves then test for leaks and proper operation

Material List:

(1) DB-5HD/RED 5 Gallon Dome Bottom Bypass Feeder by Quantrol
200 PSI (13.6 Bar) at 200° F (90° C) standard series has a 3 1/2" quarterturn positive seal closure and quick release cap
Flat or dome bottom models available in 2, 5, 12 and 18 gallon capacities
300 PSI (20.7 Bar) at 200° F (90° C) high pressure series available in 1, 2, 5 & 12 gallon capacities
Epoxy coating, stainless steel or ASME code construction available on select models

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
20	\$2,801.89	\$1,372.12	\$4,174.01