



Date: 5/8/2023

Region: 4A
FAC ID: PA118

CSS No.: 92956
Maximo Work Order No.: 12560

Asset #: NA

Original Work Request:

Neither one of the overhead doors will work automatically. These are very large doors and difficult to operate manually. Supervisor on site believes that it might be an sensor issue.

Description of Repairs Needed:

Labor and material to a.) replace 4-AA lithium ion batteries and test for proper operation

Material List:

4-AA lithium ion batteries

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
3	\$419.11	\$20.11	\$439.22