



Date: 4/25/2023

Region: 4A
FAC ID: PA063

CSS No.: 93066
Maximo Work Order No.: 12577

Asset #: NA

Original Work Request:

Repair CO2 sensor. Carbon monoxide detector is going off in alarm. Model #CM-6 and the trouble codes are T-00 & T-01.

Description of Repairs Needed:

Labor and material to a.) replace the CO detector Part # 36CF89, Model - GD-6 (Audible/Visual, Gas Detector, Controller, Transducer)

Material List:

Part # 36CF89, Model - GD-6 (Audible/Visual, Gas Detector, Controller, Transducer)

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$556.11	\$879.52	\$1,435.63