



Date: 5/24/2023

Region: 4A  
FAC ID: PA118

CSS No.: 93237  
Maximo Work Order No.: 12769

Asset #: NA

#### Original Work Request:

Repair fire protection devices.  
•Smoke Detector was in trouble upon arrival and outside speaker hanging  
•West wall horn strobe failed to flash  
•AMSA Bldg, Corridor 110 – Smoke detector in trouble upon arrival

#### Description of Repairs Needed:

Labor to a.) provide a team of fire alarm technicians to investigate and troubleshoot outstanding fire alarm deficiencies at PA118.  
Please note - a follow up quote for repairs may be needed upon troubleshooting the system.

#### Material List:

NA

#### Equipment List:

NA

#### PM WO History:

Fire Inspection March 2023

#### Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
15	\$2,073.60	\$0.00	\$2,073.60