



Date: 3/3/2023

Region: 4C
FAC ID: VA039

CSS No.: 90947
Maximo Work Order No.: 12308

Asset #: NA

Original Work Request:

Repairs needed to over crane, estimate from recommended vendor attached

Description of Repairs Needed:

Labor and material to a.) repair the crane by installing a new gear reducer b.) install a new black pendant cable using screws, retaining rotary limit cover screws, and PB screws and test for proper operation

Please note: this new RSM is for the price increase due to the age of the quote

Material List:

- (4) 29298-5U Screw Captive
- (4) 3317U Ring, Retaining Rotary Limit Cover Screw
- (1) 42621Q Gear Reducer
- (1) 26670Q Warning Label
- (6) PB Screw
- (22) 37226Q Pendant Cable Black
- (4) 3106800-5U Hood Black

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
30	\$4,343.98	\$3,975.30	\$8,319.28