

Date: 7/6/2023

Region: 4A  
FAC ID: NY010

CSS No.: 93998  
Maximo WO No.: 13368

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair the cracked ERV drive belt.

**Description of Repairs Needed:**

Labor and material to a.) remove cracked drive belt on General area ERV b.) install and supply OEM drive belt c.) Perform complete start-up

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician	\$ 3.00	\$ 109.50	\$ 328.50
			\$ -

**Material List:**

	Quantity	Cost	Total
OEM drive belt & misc materials	1	\$ 641.50	\$ 641.50
Truck Fee	1	\$ 55.00	\$ 55.00
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$328.50	\$696.50	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,025.00	\$123.00	\$61.50	\$1,209.50



**GREATER NIAGARA MECHANICAL, INCORPORATED**

7311 WARD ROAD ∞ NORTH TONAWANDA, NEW YORK 14120

PHONE 716.695.3600 ∞ FAX 716.695.3700

June 1, 2023

Quote # 23-222

Tidewater Inc.  
5835 Avenida Encinas suite 118  
Carlsbad, CA 92008

**RE: AMHERST USARC (NY010) ERV BELT**

We, at Greater Niagara Mechanical, Inc., are pleased to offer the following scope of work and pricing for your review:

**Scope:**

- Remove cracked drive belt on General area ERV
- Supply and supply OEM drive belt
- Perform complete start-up

**Cost.....\$1,025.00**

**Labor/truck.....\$383.50**

**Materials.....\$641.50**

**HVAC Exclusions**

- Shift or premium time
- Tax
- Anything not covered in above scope

Thank you for the opportunity to quote the above-mentioned project! Please feel free to contact us with any questions.

Sincerely,

Christopher Sembert  
Greater Niagara Mechanical