



Date: 3/31/2023

Region: 4C

FAC ID: WV046

CSS No.: 91987

Maximo Work Order No.: 12069

Asset #: NA

**Original Work Request:**

During safety inspection multiple exit signs failed battery test, batteries need to be replaced.

**Description of Repairs Needed:**

Labor and material to a.) to replace (12) batteries for the exit lights

**Material List:**

(12) LIT ELB1201N EMER LT NCKL-CAL BATT  
Pn: 37211  
UPC: 78423109321

**Equipment List:**

NA

**PM WO History:**

NA

**Estimate Summary:**

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$780.00	\$844.28	\$1624.28