

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY052 Date of Visit: 3.28.24

Contractor Personnel on Site:

- | | |
|------------------------|----------|
| 1. <u>Rob McIntosh</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 95247 WO# 14096


Description of Repairs

Replace Motor Starter #1. Found Starter OK,
Rew Pump Installed 8.14.23 wires wrong
causing overload to trip. Corrected wiring
checked operation. OK at this time

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Rob McIntosh Date: 3.28.24

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Daniel Taft, GS9 Date: 28 March 2024

Signed: 

E-Mail: daniel.m.taft.civ@army.mil

2



SQUARE D

PERPELIGRO

ONE OR MORE LIVE CIRCUITS
Disconnect ALL power to the
equipment before servicing.
Failure to do so may result in death
or serious injury.

CIRCUITOS ENERGIZADOS
Hay uno o más circuitos
energizados. Desconecte
todas las partes de equipo
eléctrico antes de dar servicio.
Descargas eléctricas podrían
causar la muerte o lesiones serias.

CIRCUITS SOUS TENSION
Coupez l'alimentation à cet appareil
avant de procéder à l'entretien.
Une décharge électrique entraînera la
mort ou des blessures graves.



⚠ DANGER/PELIGRO

ONE OR MORE LIVE CIRCUITS
Disconnect ALL power to the
equipment before servicing.
Failure to do so may result in death
or serious injury.

CIRCUITOS ENERGIZADOS
Hay uno o más circuitos
energizados. Desconecte
todas las partes de equipo
eléctrico antes de dar servicio.
Descargas eléctricas podrían
causar la muerte o lesiones serias.

CIRCUITS SOUS TENSION
Coupez l'alimentation à cet appareil
avant de procéder à l'entretien.
Une décharge électrique entraînera la
mort ou des blessures graves.

AUTO
OFF/O
HAND/I

ZONE #2

RESET

REESTABLECIMIENTO
REARMEMENT

ZONE #1

RESET

REESTABLECIMIENTO
REARMEMENT

