

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: _____ Date of Visit: _____

Contractor Personnel on Site:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# _____ WO# _____

Description of Repairs

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: _____ Date: _____

Signed: Julie Page

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS Date: 08/14/2024

Signed: John F. Granata

E-Mail: john.f.granata.ctr@army.mil

POSTLER & JAECKLE

PLUMBING · HEATING · AIR CONDITIONING
REFRIGERATION · SHEET METAL

24 HR EMERGENCY		1-800-724-4252	
NEW YORK OFFICES			
ROCHESTER	MAIN	585-546-7450	
	SERVICE	585-423-6214	
ALBANY	SERVICE	518-459-0910	
BINGHAMTON	SERVICE	607-757-0100	
SOUTHERN TIER	SERVICE	607-739-8303	
SYRACUSE	SERVICE	315-455-5587	
NEW JERSEY & PENNSYLVANIA		SERVICE	570-883-9563

Date	7/29/2024
Job No.	69404
Cost Code	000001906
Work Order No.	223016530
Ticket No.	20240515073850
Customer P.O.	15587

Customer US ARMY WEBSTER RESERVE CENTER (86804)
Address 515 RIDGE ROAD (NY070), WEBSTER NY 14580
Contact JOHN GRANATA (944-9099)
Description Q BREAKROOM SPLIT BLOWER BEARINGS RE- PLACEMENT PER QUOTE CSS97624 ~SEE NOTES

EQUIPMENT

Manufacturer	Model	Serial No.	Location	No.	Desc.	Parts Spec.
N/A	N/A	N/A				

WORK PERFORMED

Date Description

7/25/2024 Pick up materials from the office. Check in and start taking the unit above the ceiling apart. Cut a hole in the bottom to access bearing. Take belt and sheave off. Remove bearing collar and bearing would not move. Take screws out of bearing housing bracket but they had nuts behind. Remove and replace bearing. Install 1/4-20 nutserts to reinstall bracket. Install bracket. Cut hole in back side of unit bottom to access rear bearing. Remove bearing collar and bearing. Clean up and I will return tomorrow to finish.

7/26/2024 Check in and set up. Install rear bearing into bracket and install bracket. Adjust bearings. Install and adjust sheave on motor side. Reinstall belt and check operation. All ok. Turn back off and repair access holes with sheet metal. Put unit back together and check operation. Clean area.

MATERIAL

Category	PO No.	Description
PO	069404-190600	bearings , 2ea Freight, 1ea
Consumable		Sawzall blade, never seize, nutserts, rags, gloves. ,
Consumable		Sheet metal, screws, nutserts, aluminum tape,

LABOR

Date	Technician Name	Tech Id	ST	OT	DT	Shift	Remark
7/25/2024	Michael Deaton	01553	8.00				
7/26/2024	Michael Deaton	01553	8.00				
Total							16.00

TOOL RENTAL

Tool Description	Week Ending	M	T	W	T	F	S	S

SUBCONTRACTOR

RECOMMENDATION

Job Status	JOB STATUS COMPLETE	
Accepted By		
Tel		
Email	julie.pape@tideh20.net;	Signature
Comments		
Note: tools and materials may not reflect those listed on the final invoice.		Date

POSTLER & JAECKLE

PLUMBING · HEATING · AIR CONDITIONING
REFRIGERATION · SHEET METAL

24 HR EMERGENCY		1-800-724-4252	
NEW YORK OFFICES			
ROCHESTER	MAIN	585-546-7450	
	SERVICE	585-423-6214	
ALBANY	SERVICE	518-459-0910	
BINGHAMTON	SERVICE	607-757-0100	
SOUTHERN TIER	SERVICE	607-739-8303	
SYRACUSE	SERVICE	315-455-5587	
NEW JERSEY & PENNSYLVANIA	SERVICE	570-883-9563	

Date	7/30/2024
Job No.	69404
Cost Code	000001908
Work Order No.	223016532
Ticket No.	20240724163025
Customer P.O.	15587

Customer US ARMY WEBSTER RESERVE CENTER (86804)
Address 515 RIDGE ROAD (NY070), WEBSTER NY 14580
Contact JOHN GRANATA (944-9099)
Description Q MUA START UP PER QUOTE. CSS97624 ~SEE NOTES

EQUIPMENT

Manufacturer	Model	Serial No.	Location	No.	Desc.	Parts Spec.
N/A	N/A	N/A				

WORK PERFORMED

Date Description

7/30/2024 Unit locked out. Call tech support to unlock. Unit is password protected. Unlocked unit and found it has a bad temp sensor reading 580 degrees. Get quote for a new sensor. Go through startup with tech support for proper readings and settings. Use bypass switches to set fan and gas settings. Unit is reset for now but will go into lockout again during a call for heat with the bad temp sensor. It will think it is overheating and will lock out.

MATERIAL

Category	PO No.	Description

LABOR

Date	Technician Name	Tech Id	ST	OT	DT	Shift	Remark
7/30/2024	Michael Deaton	01553	4.00				
		Total	4.00				

TOOL RENTAL

Tool Description	Week Ending	M	T	W	T	F	S	S

SUBCONTRACTOR

RECOMMENDATION

Job Status	JOB STATUS COMPLETE	
Accepted By		
Tel		Signature
Email	julie.pape@tideh20.net;	
Comments		
Note: tools and materials may not reflect those listed on the final invoice.		Date

POSTLER & JAECKLE

PLUMBING · HEATING · AIR CONDITIONING
REFRIGERATION · SHEET METAL

24 HR EMERGENCY		1-800-724-4252	
NEW YORK OFFICES			
ROCHESTER	MAIN	585-546-7450	
	SERVICE	585-423-6214	
ALBANY	SERVICE	518-459-0910	
BINGHAMTON	SERVICE	607-757-0100	
SOUTHERN TIER	SERVICE	607-739-8303	
SYRACUSE	SERVICE	315-455-5587	
NEW JERSEY & PENNSYLVANIA	SERVICE	570-883-9563	

Customer US ARMY WEBSTER RESERVE CENTER (86804)
Address 515 RIDGE ROAD (NY070), WEBSTER NY 14580
Contact JOHN GRANATA (944-9099)
Description Q ERV MOTOR & SHEAVE REPLACEMENT PER QUOTE CSS97624 ~SEE NOTES

EQUIPMENT

Manufacturer	Model	Serial No.	Location	No.	Desc.	Parts Spec.
N/A	N/A	N/A				

WORK PERFORMED

Date Description

8/1/2024 Check in and open ERV. Disassemble cells to get to motor. Disassemble bracket and pull motor. Remove electric. Mount new motor.

8/2/2024 Tighten sheave and align motor with blower. Install electric and wire motor to 460v. Check rotation and rewire to correct rotation. Check operation. Reinstall heat recovery cells and put unit back into operation. Do final checks and clean area.

MATERIAL

Category	PO No.	Description
PO	069404-190700	Sheave, 1ea
PO	069404-190701	1.5HP motor , 1ea
Consumable		2 bolts and hardware, rags, pb blaster ,
Consumable		Zip ties, electric crimp connectors, tape,

LABOR

Date	Technician Name	Tech Id	ST	OT	DT	Shift	Remark
8/1/2024	Michael Deaton	01553	8.00				
8/2/2024	Michael Deaton	01553	8.00				
Total							16.00

TOOL RENTAL

Tool Description	Week Ending	M	T	W	T	F	S	S

SUBCONTRACTOR

RECOMMENDATION

Job Status	JOB STATUS COMPLETE	
Accepted By		
Tel		_____ Signature
Email	julie.pape@tideh20.net;	
Comments		
Note: tools and materials may not reflect those listed on the final invoice.		_____ Date

