

NY067 BLDG1

11/10/22


90129

19382

I removed the ceiling tile and found drip lines that led me to the roof , on the roof i found the tar on the seams of the vent stack housing was cracked and exposing the seams i removed the old tar and resealed the seams, then i went back inside and replaced the stained ceiling tile

11/10/22

11/10/22


Ammie. E. Marrero. Civ@army.mil

