

SERVICE REPORT

DATE 2025 12 15 ARRIVAL TIME 8:30 DEPARTURE TIME 2:00 JOB/TCK. NO. 228479

CUSTOMER P.O. NO. PO-0003567

JOB NAME/LOCATION *USARC - Rainelle WV035*

SERVICE REQUESTED *combine this invoice with WO 228476 & 228483 (20) Investment is to repair the Burner on Burnham Boiler (M#*

Manufacture: <u>Burnham</u>				
Model#: <u>V1120</u>				
Serial#: <u>65250477</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. went to the boiler shut off power removed burner checked the nozzle and spark electrodes gaps are good checked the fuel filter filter is good put the burner back in turned boiler on sparks good but failure to light checked fuel pressure fuel pressure is low removed the fuel pump checked for debris was clear found the that fuel pump spins very rough and hard spots will quote a new fuel pump picked and cleaned up and left site

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative