

SERVICE REPORT

DATE 3/8/2023

ARRIVAL TIME 11:30

DEPARTURE TIME 2:30

JOB/TCK. NO. 194245

CSS# 90112

JOB NAME/LOCATION *USARC - New River Valley Memorial VA012*

SERVICE REQUESTED *Replace HW circulating pump and Relief Valve Apex boiler SN65271233. POC Reg Cook 703-738-5307.*

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Got on site and checked in with customer. Went to the boiler room and checked the serial numbers on the boilers. Noticed that the serial number listed on the call didn't match the serial number for either of the boilers. Call was for bad relief valve and circulator pump. Started checking relief valves and all were OK, circulator pumps on both boilers were OK, however I did find that the circulator pump for the DHW tank was no good. Had 120V feeding it, capacitor OK, but pump was not running and was so hot you couldn't touch. Called Amy to get this all squared away. Looks like we received the wrong location for this call, however I still found that the DHW was down so it wasn't a waste. Amy got emergency approval for a CSS

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative

SERVICE REPORT

CUSTOMER P.O. NO. CSS# 90112

☐ Leak Tested
☐ Leak Found
☐ Leak Repaired
Method: _____
Total Charge: _____

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

[illegible][illegible]

SIGNATURE _____

Customer Representative