

SERVICE REPORT

KONECRANES®
Lifting Businesses™

Report Created: Feb 19, 2019 4:24 PM

Customer and Service Information

Customer	CMI Management Inc / US Army Reserve - Johnstown 227		
Business Location	US Army Reserve - Johnstown PA051 (PA227), Johnstown, 288 Aviation Dr		
City	Johnstown		
Agreement			
Service Request	1-88239857953		
Description	CPA- Provide labor and materials to replace pendant as per sales quote 1-ZS59GXU		
PO Number	5802		
Billing Type	Fixed		
Customer Contact	Bernie Koblinsky 703-738-5303 bernie.koblinsky@cmimgmt.com	Konecranes Contact	Thomas Yakich 4127879480 tom.yakich@konecranes.com

Assets

Yale Crane 3865

Single girder EOT - 1 trolley wire rope hoist, 5 t, Bay Crane, EWRH 5.5t YALE sn W319100A mn
CEW51/2X25RT18D3

Manufacturer	YALE	Span	35ft
Site Location	BAY CRANE / PA051-22701	Lift	28ft
Capacity/SWL	5 ton	Volt/Ph/Hz	440-3-60
Service Products	Planned Repairs		

Electrics

Control system

✓ Pushbutton pendant	Repaired
Date Reported	Feb 19, 2019
Technician	Branden Root
Task Type	Visual assessment
Fault Code	Damaged enclosure
Risk	Safety Risk
Recommendation	Replace
Comment:	Replaced pendant



Feb 19, 2019 1:52 PM Matt Hunsberger, Customer



Feb 19, 2019 1:40 PM Branden Root, Technician

Component Condition

- ✓ Acceptable (No issues detected)
- ! Need Attention

Findings and Actions

Safety Risk **WARNING**

Indicates an unsafe condition. Failure to remedy such condition before continued operation of the identified Asset may result in personal injury including death, or property damage.

Production Risk

Indicates an inefficient condition. Failure to remedy such condition before continued operation of the identified asset may result in inefficient asset performance or an interruption in production.

Undetermined Condition

Indicates that the condition could not be directly verified through visual inspection as a result of asset configuration and/or obstruction.

The condition of certain components cannot be directly verified through visual inspection without further disassembly and/or the use of other inspection methods. These advanced services are generally excluded from the scope of typical compliance and preventive maintenance inspections. Consultation Services may be added to a Service Program or offered on a stand-alone basis to assess the condition of these components. Inspection frequency for these components should follow OEM recommendations and/or governing regulations. If no records are available, we recommend appropriate inspections be carried out to determine current condition and to establish a baseline for recurring inspections.

Improvement Opportunity

Indicates a potential opportunity to improve the safety, productivity, application or useful life of the asset.

Acceptable / Repaired Item

Component condition is verified by Konecranes service technician. No actions required. If a component or other object has been repaired within the service visit, green color code is shown as well.

KONECRANES® STORE

SPARE PARTS, ACCESSORIES AND SELECT
PRE-CONFIGURED LIFTING EQUIPMENT

store.konecranes.com

ONLINE
ANY TIME

YOURKONECRANES

CRANE MAINTENANCE INFORMATION
AND REMOTE MONITORING DATA

your.konecranes.com