

SERVICE REPORT

DATE 2-9-23 ARRIVAL TIME 9:30 DEPARTURE TIME 11:00 JOB/TCK. NO. 193828

CUSTOMER P.O. NO. **CSS87316**

JOB NAME/LOCATION *USARC - Rainelle WV034*

SERVICE REQUESTED *PTACs were replaced with heat pump units, however, the old units were tied into the water loop, and will have to be*

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Was already on site. Client called me and told me when he replaced three ptac units. I went and started looking at them and seen that the piping was unhook where the hot water coil was took out and wanted to see if we could fix it because the loop needed drained. I set up ladder and looked for some different valves to shut but there was none other than the main valves in the pump room coming from the main building. Will have to drain the OMS loop to fix the piping. Put ladder back up and then down paper work.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE [Signature]

Customer Representative