

SERVICE REPORT

DATE 2026 1 14 ARRIVAL TIME 7:30 DEPARTURE TIME 8:30 JOB/TCK. NO. 230231

CUSTOMER P.O. NO. FEMS#3432865

JOB NAME/LOCATION *USARC - Rainelle WV035*

SERVICE REQUESTED *OMS shop - Ptac noise. The front office PTAC is making the same noise as the PTAC in the right office CMI just*

Manufacture: <u>GE</u>				
Model#: <u>AZ65H12DABW7</u>				
Serial#: <u>ST105486G</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. went to the oms shop turned unit on and in A/C unit would not turn on compressor due to outside temp too cold pulled unit out found heat shielding that had broken and had fell in condenser fan cover and was hitting fan blades pulled out broken pieces fan moves free and clear put unit back in wall powered unit back on heat strips worked could not get condenser fan to kick on due to temps if customer calls may have to return for unit due to outside temps today picked and cleaned up and left

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative