

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE ARRIVAL TIME DEPARTURE TIME JOB/TCK NO 200117

CUSTOMER PO. NO. CSS# 95025

JOB NAME/LOCATION USARC - Rainelle WV035

JOB NAME/LOCATION COW #10 - Hawley, WI 53541
SERVICE REQUESTED Must have signed COW.

Manufacturer: Burnham
Model#: ALLIANCE SL119
Serial#: 081150300

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Then once i did i turned power back on and boiler would not run till the pump was on and made the flow switch. Boiler ran a few minutes and kicked off but it was because the controls kicked it off and thinking it was over the sensor. Called Amy and asked for the guys number that installed the controls and talked to him about it. He said he would pull it up and take a look at it. Found that it is something in the controls that has to do with the boiler not running. He said he was going to look into it. Packed up tools and done paperwork.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE

YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative