

## CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 10/27/2023 ARRIVAL TIME \_\_\_\_\_ DEPARTURE TIME \_\_\_\_\_ JOB/TCK. NO. 201828CUSTOMER P.O. NO. CSS# 95087JOB NAME/LOCATION USARC - Beaver WV002SERVICE REQUESTED AHU # 2 in Mechanical room has visibly frozen refrigerant lines w/o 14263

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

## WORK PERFORMED/UNIT INFO.

*Was on site already to quote some HW valve actuators. Asked about the AHU and evidently it was a non issue/not heard of.*

## NATURE OF WORK

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

## PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	

## SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1350 Jordan Berry	0.50				0.50					

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Customer Representative