

SERVICE REPORT

DATE 2024 10 15 ARRIVAL TIME 6:30 DEPARTURE TIME 2:00 JOB/TCK. NO. 213955

CUSTOMER P.O. NO. CSS# 99094

JOB NAME/LOCATION USARC - Abingdon VA001

SERVICE REQUESTED *Water supply ine valve severely corroded that services the new RTU just inside the boiler room w/o 16909*

Manufacture: <u>Burnham</u>				
Model#: <u>V909A</u>				
Serial#: <u>65252689</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived and checked in and went to boiler room and Amy sent pictures of valve that needed checked. I was on wrong valve I was on boiler 3 way valve that was leaking also was asked to look at why I was there tried to tighten packing and had no luck and stem is corroded and valve needs replaced. Then looked at the right one and found that the mounting bracket had corroded off in back and valve could come lose at any time also stem is corroded on it also and valve should be replaced. Will send in a quote for repair if quote gets approved we could do repair and boiler service at same time.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____
Customer Representative