

SERVICE REPORT

DATE 2025 2 21 ARRIVAL TIME 2:00 DEPARTURE TIME 8:30 JOB/TCK. NO. 218688

CUSTOMER P.O. NO. *FEMS3071003*

JOB NAME/LOCATION *USARC - Galax VA033*

SERVICE REQUESTED *Emergency call - w/o 18261 no heat in training building. reset panel and cannot get boilers to work. OT approved*

| | | | | |
|----------------------------|-----|----|----|------|
| Manufacture: <i>Triad</i> | | | | |
| Model#: <i>OPS-1600-SH</i> | | | | |
| Serial#: <i>57828</i> | | | | |
| Refrigerant Added: | Qty | lb | oz | TYPE |
| Refrigerant Removed: | Qty | lb | oz | TYPE |

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived and checked in and went to boiler room and found that the boiler was down on flame fault so tried to reset and it would not fire so started checking and found it was not getting any oil so we did not have an oil filter we pulled filter out till we can get one and return to install them. Was able to get boiler up and running and heat in bldg. Had to look at a breaker on hot water tanks and found that they have three breakers feeding to a terminal block with three wires from each breaker for a total of 9 #12 wires then out with 3 #1 to a 100 amp disconnect to feed hot water heater . The breakers are 2-20 amp, 1-25 amp 3 ph breaker needs to be replaced with one 100 amp breaker like the other tank has to make it safe. We then looked at the hot water heaters and

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES _____ NO X EXPLAIN need to return and replace oil filters and work up quotes

SIGNATURE _____
Customer Representative

SERVICE REPORT

DATE _____ ARRIVAL TIME 9:27 am DEPARTURE TIME _____ JOB/TCK. NO. 218688

CUSTOMER P.O. NO. FEMS3071003

JOB NAME/LOCATION *USARC - Galax VA033*

SERVICE REQUESTED

| | | | | |
|----------------------------|-----|----|----|------|
| Manufacture: <i>Triad</i> | | | | |
| Model#: <i>OPS-1600-SH</i> | | | | |
| Serial#: <i>57828</i> | | | | |
| Refrigerant Added: | Qty | lb | oz | TYPE |
| Refrigerant Removed: | Qty | lb | oz | TYPE |

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

found that they had unwired some of the heaters to make it work will quote repairing them. Also found that the hot water pump #2 has a leaking seal and that pump #1 was valved off due to seal being bad on it because it had flooded the boiler room floor will work up quote for that also. Will work up quote to get other boiler up and running it needs a burner replacement.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative