

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2025 7 22 ARRIVAL TIME 7:30 DEPARTURE TIME 11:30 JOB/TCK. NO. 213833CUSTOMER P.O. NO. PO-00013870JOB NAME/LOCATION USARC - Rainelle WV035SERVICE REQUESTED (10) PRICING VERIFIED ON 4/3 - Investment is to replace (2) Taco Pumps (M# 0010-F3) that circulate the water in (2)

Manufacture: <u>Apex</u>				
Model#: <u>APX500F-2L07</u>				
Serial#: <u>65271233</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Went to boiler room and looked to see what i needed to change out the pumps. I then got my tools and made sure power was off the pump. I then unwired it and shut the valves below and above it. I then took out the bolts holding the pump and took it out. I then went and looked at the new one and found that it was to small to fit and needed to be long on the piping. I then put it back and bolted it back in. I called to see if i could find a different pump to fit. I then pulled out the other pump because it was the same size. Once i got the new one in, I tested the motor and made sure it worked. I then got the info off one boiler that the stage controller was bad. then put tools away and done paper work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
2		5W305 0010F TACO PUMP		R.E.	253111

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1154 Shawn Shelton	4		1		5					

JOB COMPLETE YES _____ NO X EXPLAIN new a different pump

SIGNATURE _____

Customer Representative