

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2025 4 2 ARRIVAL TIME 11:30 DEPARTURE TIME 2:30 JOB/TCK NO 215657

DEPARTURE TIME 2:30 JOB/TCK. NO. 215657

JOB/TCK. NO. 215657

CUSTOMER PO. NO. 509803

JOB NAME/LOCATION USARC - New River Valley Memorial VA012

**SERVICE REQUESTED** (12) *Investment is to replace the DHW Circulator Pump and Motor.*

Manufacture:			
Model#:			
Serial#:			
Refrigerant Added:	Qty	lb	oz
Refrigerant Removed:	Qty	lb	oz

- Leak Tested**
- Leak Found**
- Leak Repaired**

**Method:** \_\_\_\_\_

**Total Charge:** \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

Got on site and checked in with customer. Went to the boiler room and started replacing the DHW booster pump. Got it out, and the new one installed. Turned valves back on for it and leak checked it, all looked good. Wired it back up and then turned it on. Bled some air off of it by opening up the closest HW spigot. All looked good on it. Still need a HW tank circulator pump though for the domestic hot water to work. I quoted a new pump for that. Packed up tools, did all my paperwork, and then left when finished.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

JOB COMPLETE YES  NO  EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**