

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2025 6 9 ARRIVAL TIME 8:30 DEPARTURE TIME 10:30 JOB/TCK. NO. 217002CUSTOMER P.O. NO. PO-00008150JOB NAME/LOCATION USARC - Galax VA033SERVICE REQUESTED (8) Investment is to replace the BFP (M# 975X; S# 921338). -
Customer is in charge of having BF certified

Manufacture: <u>Wilkins-Zum</u>				
Model#: <u>975XL</u>				
Serial#: <u>403038</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived checked in and valved off BFP and removed old one and installed new one and turned on water and checked for leaks had none.
Old BFP had an Asset#7210 BFP / VA033-00 did not have a new tag for new one.
See photos

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		Amer	251681
1		975LF-7 WILKIN 3/4 975XL2 BFP		Amer	251681

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
58 Mark Bass	4				4					

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative