

SERVICE REPORT

DATE 2025 2 27 ARRIVAL TIME 11:00 DEPARTURE TIME 2:00 JOB/TCK. NO. 218817

CUSTOMER P.O. NO. *WV006 WO18269 FEMS30*

JOB NAME/LOCATION *USARC - Cross Lanes WV006*

SERVICE REQUESTED *Emergency 2hrs- 4 boilers at the training facility # 1 Boiler is down waiting parts. Boilers #2 and #3 are now running*

| | | | | |
|----------------------|-----|----|----|------|
| Manufacture: _____ | | | | |
| Model#: _____ | | | | |
| Serial#: _____ | | | | |
| Refrigerant Added: | Qty | lb | oz | TYPE |
| Refrigerant Removed: | Qty | lb | oz | TYPE |

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived at site and checked in with customer then looked at boilers. Boilers 2 and three had high temp difference across heat exchanger i checked the pumps and impellers they where in good condition then i looked at boiler 3 Found bad capacitor for combustion blower then checked out with customer.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative