

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2025 7 11 ARRIVAL TIME 7:30

DEPARTURE TIME 11:30

JOB/TICK NO 223703

CUSTOMER PO. NO. FEMS 3190136

JOB NAME/LOCATION USARC - Lewisburg WV024

SERVICE REQUESTED Daikin system in E2 Error. System not running w/o 19209

Manufacturer: Daikin
Model#: REMQ72PATJ
Serial#: A000298

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Arrived on site. Had to wait till client arrived to let me in. Once I got in he showed me the controller. I looked up the codes and it was compressor nut running and condenser fan signal loose. I then went out to the condenser and ohmed out the compressors and fan motors. All of them checked out good. I then checked the pressures and found that the system was flat on freon. It seems that every time i get a service call here that the unit is always flat on gas. Highly recommend to replace the system due to all the problems they have had out of these units. I then called and told Reginal what i had found and he said to quote out to repair the system. I then put panels back on units and done paper work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE

YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative