

## Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
<b>TOTAL*:</b>	<b>\$0.00</b>				
* Not including taxes					

## Service Forms

**Daily Form** Fill out every day, even on PMs, and projects


**TECH NAME** Tim Diamond  
**DATE** 7/31/2025  
**POINT OF CONTACT:** Cindy  
**DESCRIPTION OF WORK PERFORMED** troubleshoot AHU6. found that the bearing on the back side of the ahu was busted, the compression ring set screw broke, causing the bearing to fall out of place.  
**TOOLS USED** handtools  
**MATERIALS USED OR PICTURE OF TAG\*** n/a  
**HOURS** REGULAR:  
OVERTIME:

---

### Before Picture

#### Before Picture

20250731\_131613.jpg.jpg



## Attachments

## Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
<b>TOTAL*:</b>	<b>\$0.00</b>				
* Not including taxes					

## Service Forms

Daily Form	Fill out every day, even on PMs, and projects
TECH NAME	Tim Diamond
DATE	8/27/2025
POINT OF CONTACT:	Cindy
DESCRIPTION OF WORK PERFORMED	replaced bearing on AHU 6. was not able to get into controls to start unit. will return tomorrow to start unit  returned next day and unit ran
TOOLS USED	handtools
MATERIALS USED OR PICTURE OF TAG*	1 bearing bought for job
HOURS	REGULAR:  OVERTIME:

## Attachments