

## SERVICE REPORT

DATE 2025 12 30 ARRIVAL TIME 7:30 DEPARTURE TIME 3:00 JOB/TCK. NO. 229644

CUSTOMER P.O. NO. \_\_\_\_\_

**JOB NAME/LOCATION** *USARC - Abingdon VA001*

**SERVICE REQUESTED** *Pump and vent cover, roof cap needed on condensing boiler 1(left small boiler) water is leaking in when it rains.*

Manufacture: <u>B &amp; G</u>				
Model#: <u>172556</u>				
Serial#: <u>859003</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Arrived and checked in and got into boiler room and looked at the B&G pump that was bad and got the info off of pump so we can quote one and also looked at the leak on the condensing boilers and went to roof and found that someone had put some sealant around flue pipes. Did look at the flue on main boiler and found were it needs to be resealed were it goes in to chimney will put a quote in for that also.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

#### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

### SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Customer Representative