

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

CUSTOMER P.O. NO. CSS# 95962

JOB NAME/LOCATION USARC - New River Valley Memorial VA012

SERVICE REQUESTED RTU is running. Everything is running but the air is cold. w/o
14532 CSS 95962

Manufacture: Trane
Model#: SLHFC404
Serial#: C99G12489M

| Refrigerant Added: | Qty | lb | oz | TYPE |
|----------------------|-----|----|----|------|
| Refrigerant Removed: | Qty | lb | oz | TYPE |

- Leak Tested
- Leak Found
- Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

not letting the power through. The boiler had water in it and the pump was running so I jumped it out and the boiler fired up and started running. I then took the jumper off and I got the info off boiler to order a new one. Put away tools and then done paper work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative