

SERVICE REPORT

DATE 2025 8 4 ARRIVAL TIME _____ DEPARTURE TIME _____ JOB/TCK. NO. 220607

CUSTOMER P.O. NO. FEMS 3113822, WO 192

JOB NAME/LOCATION USARC - South Ridge WV007

SERVICE REQUESTED (36) Investment is to replace the Compressor, Filter Drier, and Charge Trane Chiller (M# CGAM080; S# U15B47125).

Manufacture: <u>Trane</u>				
Model#: <u>CGAM080A2L02AXD2A1A1A1AX</u>				
Serial#: <u>U15B47125</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Picked up compressor from the shop and went to jobsite. Pumped down and recovered refrigerant from circuit 2 . Removed oil from compressors and removed old compressor. Installed new compressor and pressurized system. Found no leaks with nitrogen pressure test. Pulled vacuum to get oil back into compressors. Cleaned up all tools and work area's. Will return tomorrow to charge system up and turn chiller back on.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES _____ NO X EXPLAIN _____

SIGNATURE _____

Customer Representative