

## SERVICE REPORT

DATE 2024 7 23 ARRIVAL TIME 10:00 DEPARTURE TIME 12:00 JOB/TCK. NO. 208769

CUSTOMER P.O. NO. CSS98180

**JOB NAME/LOCATION** USARC - South Ridge WV007

**SERVICE REQUESTED** (9) Investment is the clean the Condenser Coils, Filters, Leak Test, and Charge Carrier CU (M# 38MAQB12; S#

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	3 lb	0 oz	410A TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Arrived on site checked in with customer. Pulled vaccum to 500 microns. Let it settle for 15 minutes to perform decay test. Charged unit with 3 lbs of R410a. Checked operation and unit is operating ok at this time.

## NATURE OF WORK

Regular Service \_\_\_\_\_  
Quoted Service \_\_\_\_\_  
Start-up/Warranty \_\_\_\_\_  
SPD \_\_\_\_\_  
Contract Service \_\_\_\_\_  
Energy Management \_\_\_\_\_

#### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

## SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

**Customer Representative**