

SERVICE REPORT

DATE 2025 8 5 ARRIVAL TIME _____ DEPARTURE TIME _____ JOB/TCK. NO. 220607

CUSTOMER P.O. NO. FEMS 3113822, WO 192

JOB NAME/LOCATION *USARC - South Ridge WV007*

SERVICE REQUESTED (36) Investment is to replace the Compressor, Filter Drier, and Charge Trane Chiller (M# CGAM080; S# U15B47125).

Manufacture: <i>Trane</i>				
Model#: <i>CGAM080A2L02AXD2A1A1A1AX</i>				
Serial#: <i>U15B47125</i>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Pulled vacuum on chiller to 230 microns. Added recovered refrigerant to the system and turned chiller on. Watched chiller run and checked out new compressor and whole system operation. Everything is working as should and keeping chilled water at set point. Cleaned up all tools and work areas.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative