

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2024 8 22 ARRIVAL TIME DEPARTURE TIME JOB/TCK. NO. 212215

CUSTOMER PO. NO. WO16602/CSS98841

JOB NAME/LOCATION USARC - Cross Lanes WV006

**SERVICE REQUESTED** (64) *Investment is to repair the Glycol Leak on the Piping.*

Manufacture:				
Model#:				
Serial#:				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

**Method:** \_\_\_\_\_

**Total Charge:** \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

Picked up fittings and press tool to complete piping. Fixed leak in 3in pipe and added 3in ball valve in glycol line. Fixed pipes where we had to drill holes to drain.

Completed hooking up pipes that was left undone from other company. Cleaned up all tools and materials.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**