

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2024 7 22 ARRIVAL TIME 800 DEPARTURE TIME _____ JOB/TCK. NO. 208768CUSTOMER P.O. NO. CSS98180JOB NAME/LOCATION USARC - South Ridge WV007SERVICE REQUESTED (9) Investment is the clean the Condenser Coils, Filters, Leak Test, and Charge VRF CU (M# YN024GMF; S#

Manufacture: <u>Pioneer</u>				
Model#: <u>YN024GMF122RPD</u>				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Cleaned coils leak tested found leak on flare nut reflared both lines pulled vac to 500 micron charged start unit tomorrow

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
6		410 A			

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
85 James H. Starcher	6				6					
1424 Blake Buzzard	6				6					

JOB COMPLETE YES _____ NO X EXPLAIN _____

SIGNATURE _____

Customer Representative