

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2024 8 23 ARRIVAL TIME 12:49 pm

**DEPARTURE TIME**

JOB/TCK. NO. 212215

CUSTOMER PO. NO. WO16602/CSS98841

JOB NAME/LOCATION **USARC - Cross Lanes WV006**

**SERVICE REQUESTED** (64) *Investment is to repair the Glycol Leak on the Piping.*

Manufacture:				
Model#:				
Serial#:				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

**Method:** \_\_\_\_\_

**Total Charge:** \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

Pumped all glycol back into system and ran pumps to be able to get all glycol back in. Checked for leaks in our piping. Cleaned up all tools and material. Took empty glycol drums back to shop for further use.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

**JOB COMPLETE**

YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

**SIGNATURE**

### Customer Representative