

## CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2024 7 23 ARRIVAL TIME 800 DEPARTURE TIME 1000 JOB/TCK. NO. 208768CUSTOMER P.O. NO. CSS98180JOB NAME/LOCATION USARC - South Ridge WV007SERVICE REQUESTED (9) Investment is the clean the Condenser Coils, Filters, Leak Test, and Charge VRF CU (M# YN024GMF; S#

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

## WORK PERFORMED/UNIT INFO.

*Started up comp pulling 8 amps had fault P4 called factory found out compressor over load has bad compressor quote repairs*

## NATURE OF WORK

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

## PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
6	R-410A	R-410A Refrigerant			

## SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
85 James H. Starcher	2				2					
1424 Blake Buzzard	2				2					

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Customer Representative